	Туре	L #	Hits		DBs	Time Stamp	Comment	
1	BRS	L1	22829 4	(fus\$5 or fix\$5 or heat\$5) SAME (external)	USPAT; EPO; JPO; DERWENT			
2	BRS	L6	84990	1 and pressure	USPAT; EPO; JPO; DERWENT			
3	BRS	L11	2291	6 and (external NEAR5 heater)	USPAT; EPO; JPO; DERWENT	· ·		
4	BRS	L16	550	11 and (internal NEAR5 heat\$5)	USPAT; EPO; JPO; DERWENT			
5	BRS	L21	79	16 and elast\$5	USPAT; EPO; JPO; DERWENT			
6	BRS	L26	8	21 and (tungsten NEAR5 halogen)	USPAT; EPO; JPO; DERWENT			
7	BRS	L31	8	26	USPAT	2002/03/0 6 14:09		
8	BRS	L32	25046	((fus\$5 or fix\$5 or heat\$5) NEAR3 roll\$5) WITH (press\$5 NEAR3 roll\$5)	USPAT; EPO; JPO; DERWENT			
9	BRS	L37	4942	32 and (internal or external)	USPAT; EPO; JPO; DERWENT			
10	BRS	L42	1693	37 and elast\$5	USPAT; EPO; JPO; DERWENT			
11	BRS	L4.7	11	42 and (tungsten NEAR5 halogen)	USPAT; EPO; JPO; DERWENT			